

Conxall Corporation
601 East Wildwood Avenue
Villa Park, IL 60181
Tel (630) 834-7504
Fax (630) 834-8540
www.conxall.com



DISCLOSURE STATEMENT – CONFLICT METALS ACT

Tin, Tantalum, Tungsten and/or Gold sourced from mines in the
Eastern Democratic Republic of the Congo (DRC)

The Frank-Dodd Act, Section 1502 regarding conflict materials (metals) sets a disclosure requirement that calls upon Conxall Corporation to determine whether any products contain conflict metals. This is performed by requesting supply chain due diligence and reporting any traceable conflict metals to the Security and Exchange Commission (SEC).

Conxall Corporation includes nickel, gold and silver as surface plating metals and/or tin and lead as alloying elements for some metal contacts, terminals, solder and components used in many of our products. Conxall Corporation relies on the non-conflict information provided to Conxall Corporation by the supply chain. To the best knowledge of Conxall Corporation there is no intended use of conflict metals in the manufacturer of any Conxall Corporation products.

Tantalum and Tungsten are not used in any Conxall Corporation products.

Conxall P/Ns:

ALL

The signature below certifies that the statements above are valid and accurate.

Signature: 

Date: March 7, 2013

Name: **John Titlow**

Phone: **(630) 834-7504, Ext 4033**

Title: **Product Support Engineer**

E-mail: jtitlow@conxall.com